



المهنة العامة للطيران المدني
General Authority of Civil Aviation

CERTIFICATE OF APPROVAL

NUMBER: AMO- 242F

This certificate is issued to

HAWKER PACIFIC AEROSPACE

whose business address is

11240 SHERMAN WAY, SUN VALLEY
CALIFORNIA-91352, U.S.A.

upon finding that its organization complies in all respects with the requirements of the General Authority of Civil Aviation Regulations relating to the establishment of an Approved Repair Station and is empowered to operate with the following ratings:

ACCESSORIES
LIMITED AIRFRAME
LIMITED SPECIALIZED SERVICES

This certificate unless cancelled, suspended, or revoked, shall continue in effect until 07 JAN. 2011

Date Issued: 19 MAY 1998 Date Reissued: 18 JAN. 2010

BY DIRECTION OF THE PRESIDENT OF GENERAL AUTHORITY OF CIVIL AVIATION (GACA)

CAPT. MOHAMMED ALI JAMJOM

VICE PRESIDENT
SAFETY & ECONOMIC REGULATIONS
GENERAL AUTHORITY OF CIVIL AVIATION
KINGDOM OF SAUDI ARABIA



THIS CERTIFICATE IS NOT TRANSFERABLE AND ANY MAJOR CHANGE IN THE BASIC FACILITIES, OR IN THE LOCATION THEREOF SHALL BE IMMEDIATELY REPORTED TO THE VICE PRESIDENT, SAFETY & ECONOMIC REGULATIONS DEPARTMENT.

Repair Station Operations Specification

(Continuation)

Limitations:

Page 1 of 2

The rating(s) set forth on Certificate Number AMO- 242F is / are limited to the following:

CLASS RATINGS:

ACCESSORIES CLASS 1:	MECHANICAL
ACCESSORIES CLASS 2:	ELECTRICAL
ACCESSORIES CLASS 3:	ELECTRONIC

LIMITED RATINGS:

=====

AIRFRAME : LANDING GEAR ON THE FOLLOWING MAKES AND MODEL.

AIRBUS	:	A300, A310, A319.
BOEING	:	707, 717, 727, 737, 747, 757, 767, 777 ALL SERIES.
CONVAIR	:	440, 580.
GULFSTREAM	:	1159.
LOCKHEED	:	L1011, C-130/L382.
McDONNELL DOUGLAS:		MD11, MD90.

SPECIALIZED SERVICES:

HARD CHROME	-	BOEING STANDARD OVERHAUL PRACTICES CHAPTER 20 BAC 5709, DPS 9.71, AMS 2406, MIL-SPEC QQ-C-320.
CADMIUM PLATE	-	BOEING STANDARD OVERHAUL PRACTICES CHAPTER 20 BAC 5701, DPS 9.28, BAC 5804, AMS 2401, MIL-STD-1500.
NITAL ETCH	-	BOEING STANDARD OVERHAUL PRACTICES CHAPTER 20 BAC 5436, DPS 4.715, AMS 2649, MIL-I-6870.
PASSIVATION	-	BOEING SPECIFICATION 5751, DPS 9.07, MIL-SPEC-QQ-P-35.
SULFAMATE NICKEL-	-	BOEING SPECIFICATION 5746, DPS 9.76, AMS 2403 & 2423, MIL-P-27418.

Delegated authorities: NONE

Date Issued: 18 JAN. 2010

BY DIRECTION OF THE PRESIDENT OF GENERAL AUTHORITY OF CIVIL AVIATION (GACA)



PETER LOTT

DIRECTOR OF AIRWORTHINESS
SAFETY & ECONOMIC REGULATIONS
GENERAL AUTHORITY OF CIVIL AVIATION
KINGDOM OF SAUDI ARABIA



Repair Station Operations Specification

(Continuation)

Limitations:

Page 2 of 2

The rating(s) set forth on Certificate Number AMO- 242F is / are limited to the following:

LIMITED RATINGS: (CONTINUED)

=====

SPECIALIZED SERVICES: (CONT'D..)

NON-DESTRUCTIVE INSPECTION:

- MAGNETIC PARTICLE INSPECTION – BOEING STANDARD OVERHAUL PRACTICES, CHAPTER 20, BAC 5424, DPS 4.704, AMS 2301, ASTM-E-1444.
- PENETRANT INSPECTION - BOEING STANDARD OVERHAUL PRACTICES CHAPTER 20, BAC 5423, DPS 4.707, AMS 2647, MIL-STD-6866, ASTM-E-1417/95.
- HARDNESS INSPECTION – BOEING STRUCTURAL REPAIR MANUAL CHAPTER 50, AMS 2685, ASTM-E-18.
- ULTRASONIC INSPECTION – BAC 5439, BSS 7351, DPS 4.713, AMS 2630, MIL-HDBK-728/6.
- EDDY CURRENT – BAC 5963, DPS 4.751, MIL-HDBK-728/2.

ALL SAUDI ARABIAN REGISTERED AIRCRAFT MUST BE MAINTAINED IN ACCORDANCE WITH SAUDI ARABIAN CIVIL AIR REGULATIONS, I.E. U.S. FEDERAL AVIATION REGULATIONS (FARs).

Delegated authorities: NONE

Date Issued: 18 JAN. 2010

BY DIRECTION OF THE PRESIDENT OF GENERAL AUTHORITY OF CIVIL AVIATION (GACA)



PETER LOTT

**DIRECTOR OF AIRWORTHINESS
SAFETY & ECONOMIC REGULATIONS
GENERAL AUTHORITY OF CIVIL AVIATION
KINGDOM OF SAUDI ARABIA**

